

S.N. 10/743,851
Art Unit: 2611

IN THE DRAWINGS

Please replace the drawings with the enclosed drawings.



1 / 4





FIG. 1

130 ↗

2/4

FIG. 2
 PRIOR ART






FIG. 3A




FIG. 3B




FIG. 3C $\frac{3}{4}$

FIG. 3D

4/4




FIG.4

$$F = \begin{bmatrix} f_k & \dots & f_{2k+1} & 0 & 0 & \dots & 0 & 0 & 0 \\ f_{k-1} & \dots & f_{2k} & f_{2k+1} & 0 & \dots & 0 & 0 & 0 \\ f_{k-2} & \dots & f_{2k-1} & f_{2k} & f_{2k+1} & \dots & 0 & 0 & 0 \\ \dots & \dots \\ 0 & \dots & 0 & 0 & 0 & f_0 & \dots & f_{k-1} & f_k \end{bmatrix}$$

FIG.5